

SERVICE UPDATE

Date: 1 July 2015

Topic: Effects and implications 03.2015 firmware

Models: Kyocera TK3100/3110/3130/3150/TK1110/1115/1120/1125

New model compatibility after newest firmware update: 2L2 3F00.015.016 2015.03.12 (03.2015FW)

OEM ref	For use in:
TK3100	FS-2100, ECOSYS M3040dn, ECOSYS M3540dn
TK3110	FS-4100DN
TK3130	FS-4200DN, FS-4300D; ECOSYS M3550idn, ECOSYS M3560idn
TK3150	ECOSYS M3040idn, ECOSYS M3540idn
TK1110	FS-1040
TK1115	FS-1041, FS1220MFP, FS-1320MFP
TK1120	FS-1060DN
TK1125	FS-1061DN, FS-1325MFP

Biggest changes after 2L2 3F00.015.016 2015.03.12 (03.2015FW):

OEM ref	Does not accept:
TK3100	FS-4200, FS-4300, M3550, M3560
TK3110	FS-2100, FS-4200, FS-4300, M3040/3540/3550/3560
TK3130	FS-2100, M3040/3540

Please update your product catalog and communicate this background to your customers.



**NEW
RELEASE!**

